



DOOR DETAIL



TRIM DETAIL



IMPORTANT NOTE:

TO ENABLE EMERGENCY TRIM TO FUNCTION,
THE TURN PIECE SPINDLE MUST BE CUT TO
EXTEND NO FURTHER THAN HALFWAY THROUGH
THE DOOR.

EFFECTIVE: 5-1-88
2.11.88

B BALDWIN

0404 EMERGENCY RELEASE TRIM

TEMPLATE NO. VARIATIONS

TEMPLATE NO.

A165