


DOOR DETAIL

TRIM DETAIL



IMPORTANT NOTE:

TO ENABLE EMERGENCY TRIM TO FUNCTION, THE TURN PIECE SPINDLE MUST BE CUT TO EXTEND NO FURTHER THAN HALFWAY THROUGH THE DOOR.

EFFECTIVE: 5-1-88 *Ad 23*

B. BALDWIN	
0405 EMERGENCY RELEASE TRIM	
TEMPLATE NO. VARIATIONS	TEMPLATE NO.
	A166