



DOOR DETAIL



TRIM DETAIL



IMPORTANT NOTE:

TO ENABLE EMERGENCY TRIM TO FUNCTION,
THE TURN PIECE SPINDLE MUST BE CUT TO
EXTEND NO FURTHER THAN HALFWAY THROUGH
THE DOOR.

EFFECTIVE: 5-1-88 R. H. King

BALDWIN	
0416 EMERGENCY RELEASE TRIM	
TEMPLATE NO. VARIATIONS	TEMPLATE NO.
	A175